

**Total Land Subsidence in the Fort Grant Rd and Willcox Areas, Cochise County
Based on Radarsat-2 Satellite Interferometric Synthetic Aperture Radar (InSAR) Data**


© MDA 2011 - 2013

Time Period of Analysis: 1.9 Years 04/30/2011 To 03/26/2013


Explanation

04/30/2011 To 03/26/2013

Total Land Subsidence



- Subsidence Feature
- Hardrock
- Earth Fissures
- Cities/Towns
- Highways and Interstates**
- Interstate
- US
- State
- Roads
- Roads
- Railway



1:200,000

0 1 2 4 6 8 Miles

Decorrelation (white areas) are areas where the phase of the received satellite signal changed between satellite passes, causing the data to be unusable. This occurs in areas where the land surface has been disturbed (i.e. bodies of water, snow, agriculture areas, areas of development, etc).

Earth fissures were mapped by the Arizona Geological Survey.
For information on earth fissures visit: www.azgs.gov/EFC

Coordinate System: NAD 1983 UTM Zone 12N
Projection: Transverse Mercator
Datum: North American 1983
Units: Meter
Created: 10/24/2014

